

Continuous Radon Monitor

Model Number: 1028
Calibration Date: 03/20/2009
Monitor Time: 10/12/2009 15:15

Serial Number: 49745162
CF: 2.69

Inspector Information

Radon Services of Kansas
4932 Kimberly Ln.
Wichita
KS-67204
Phone Number: 316-821-9611

Customer Information

SAMPLE
123 n.MAIN
WICHITA
KS-00000
Phone: 000-000-0000


Site & Condition

Wind: NA
Year Built: NA
SqFt: NA
Atmospheric Condition: NA
Structure Type: NA
Monitor Location: NA

Test Summary

Start Time: 09/25/2009 12:37
End Time: 09/27/2009 12:37
Measurement Interval(hr): 1.0
Elapse Time: 2 Days 0 hrs
Overall Avg: 0.5 pCi/l
EPA Avg: 0.4 pCi/l

Continuous Radon Monitor



b ◆ Radon pCi/l b ● Motion Errors e — Temp F e — Rel % Humidity e — Press inHg

***** 09/25/2009 *****

Time	Counts pCi/l	Flags
13:37	0.4	
14:37	0.4	
15:37	1.5	
16:37	1.9	
17:37	0.4	
18:37	0.4	
19:37	0.0	
20:37	0.4	
21:37	0.0	
22:37	0.7	
23:37	0.4	

***** 09/26/2009 *****

Time	Counts pCi/l	Flags
00:37	0.0	
01:37	0.0	
02:37	0.7	
03:37	0.0	
04:37	0.0	
05:37	0.7	
06:37	0.0	
07:37	0.4	
08:37	1.1	
09:37	0.7	
10:37	0.4	
11:37	0.4	
12:37	0.0	
13:37	0.4	
14:37	0.0	M
15:37	0.0	
16:37	0.0	
17:37	0.7	
18:37	0.4	
19:37	0.0	
20:37	0.0	
21:37	0.4	
22:37	0.0	
23:37	0.0	

***** 09/27/2009 *****

Time	Counts pCi/l	Flags
00:37	1.5	
01:37	0.4	
02:37	0.4	

***** 09/27/2009 *****

Time	Counts pCi/l	Flags
03:37	0.4	
04:37	1.5	
05:37	1.1	
06:37	0.7	
07:37	0.0	
08:37	0.4	
09:37	1.9	
10:37	0.7	
11:37	0.7	
12:37	1.5	

Error Flags:

M Motion:

Inspector Signature _____

PC Software Version: 2.1.3.0

Embedded Software Version: 106